Victorian Gables Architecture Committee Q2 2023 Report April 5, 2023

Maintenance/Replacement Work Needing to Be Done Soon

- 1. Garage Door Painting Unit 9 & 26
- 2. Deck Support Post Repair Unit #4 (rotting); no cost from Kestrel Builders (Don Scott)
- **3.** Deck Surface No Longer Flat Unit #32 (support beam warped); time and materials from Kestrel Builders
- Mold from Water Seepage Around Window Well Unit 36 (evaluate); window well contractor to take care of it, but may not happen until next year. Add more dirt for temporary fix.
- **5.** Add Dirt Around New Window Wells Units 2 front, 13 front, 14 front, 17 rear and what do we do with the bottomless pit at the phone box?, 19 rear, 26 both on the side need a decent amount of dirt, 27 rear, 32 front and side
- 6. Roof Repairs for Water Leakage on Front Door Porch Unit 2; contact NoCo Roofing

Maintenance Anticipated for 2023

- **1.** Gutter Cleaning (2x, budget \$2200)
- 2. Painting (budget \$5000)
- **3.** Tuckpointing Unit 36
- 4. Gutter and Downspout Repair Units 16, 32
- 5. Gutter Leaf Guards -

Replacements Anticipated for 2023

- 1. Window Wells (15 to 16 total, budget \$27,000) Units 3, 37, others TBD
- **2.** Skylights (1 likely, budget \$1500)
- 3. Garage Doors (2 total, budget \$4500) Units TBD
- 4. Concrete Sidewalks/Driveways (budget \$6000) Units TBD